

CERTIFICATE OF COMPLIANCE

Certificate Number E244889
Report Reference E244889-20110705
Issue Date 2020-AUGUST-22

Issued to: TELEGAERTNER KARL GAERTNER GMBH
LERCHENSTR 35
71144 STEINENBRONN, GERMANY

This certificate confirms that representative samples of

Communications-, Audio/Video-, Data- and Other Signaling-circuit Accessories
See addendum page

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 1863 - Communications-Circuit Accessories
CSA C22.2 No. 182.4 - Plugs, Receptacles, and Connectors for Communication Systems
CSA C22.2 No. 233-17 - Cords and Cord Sets for Communication Systems

Additional Information:

See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E244889
Report Reference E244889-20110705
Issue Date 2020-AUGUST-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Modular patch cords: L0000M0081, L00001M0084, L00002M0112, L00003M0055, L00004M0054, L00005M0027, L00006M0033, L00000M0073, L00000M0082, L00001M0085, L00002M0113, L00003M0056, L00000M0075, L00000M0084, L00001M0087, L00002M0115, L00003M0058, L00000M0074, L00000M0083, L00001M0086, L00002M0114, L00003M0057, L00000M0076, L00000M0085, L00001M0088, L00002M0116, L00003M0059, L00003A0049, L00000N0072, L00000N0081, L00001N0084, L00002N0112, L00003N0055, L00004N0054, L00005N0027, L00000A0096, L00001A0097, L00002A0125, L00003A0066, L00000A0230, L00000A0072, L00000A0081, L00001A0090, L00001A0084, L00002A0119, L00002A0112, L00003A0062, L00003A0084, L00003A0148, L00003A0055, L00004A0104, L00004A0093, L00004A0054, L00004A0094, L00005A0067, L00005A0068, L00005A0027, L00006A0187, L00006A0119, L00006A0033, L00006A0108, L00006A0036, L00006A0034, L00006A0057, L00006A0035, L00000A0233, L00000A0075, L00000A0084, L00001A0129, L00001A0206, L00001A0087, L00002A0184, L00002A0115, L00003A0131, L00003A0132, L00003A0058, L00004A0131, L00004A0057, L00004A0152, L00005A0030, L00006A0190, L00006A0045, L00006A0046, L00006A0047, L00006A0194, L00006A0048, L00000A0182, L00000A0183, L00001A0153, L00002A0170, L00003A0116, L00004A0106, L00005A0077, L00006A0123, L00006A0124, L00006A0125, L00000A0231, L00000A0073, L00000A0082, L00001A0168, L00001A0085, L00002A0113, L00003A0101, L00003A0056, L00004A0129, L00004A0055, L00005A0028, L00006A0188, L00006A0037, L00006A0038, L00006A0039, L00006A0040, L00000A0232, L00000A0074, L00000A0452, L00000A0083, L00001A0167, L00001A0086, L00002A0185, L00002A0114, L00003A0133, L00003A0102, L00003A0057, L00004A0130, L00004A0165, L00004A0056, L00004A0119, L00005A0091, L00005A0029, L00006A0189, L00006A0041, L00006A0042, L00006A0043, L00006A0044, L00000A0234, L00000A0076, L00000A0085, L00001A0092, L00001A0088, L00002A0213, L00002A0116, L00003A0184, L00003A0185, L00003A0186, L00003A0059, L00004A0132, L00004A0058, L00005A0031, L00006A0191, L00006A0049, L00006A0050, L00006A0051, L00006A0195, L00006A0052, L00000A0235, L00000A0077, L00000A0086, L00001A0169, L00001A0089, L00002A0117, L00003A0060, L00004A0133, L00004A0060, L00005A0032,



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E244889
Report Reference E244889-20110705
Issue Date 2020-AUGUST-22

L00006A0192, L00006A0053, L00006A0054, L00006A0055, L00006A0056,
L00000A0236, L00000A0279, L00000A0130, L00000A0131, L00001A0171,
L00001A0123, L00002A0141, L00003A0085, L00004A0071, L00005A0051.

L00000A0237, L00000A0238, L00000A0226, L00001A0195, L00001A0194,
L00002A0195, L00003A0147, L00004A0134, L00005A0103, L00000A0246,
L00001A0198, L00002A0198, L00003A0150, L00004A0137, L00005A0107,
L00006A0199, L00006A0200, L00006A0201, L00000A0118, L00000A0120,
L00001A0117, L00002A0139, L00003A0078, L00005A0104, L00006A0196,
L00000A0102, L00000A0103, L00001A0099, L00002A0120, L00003A0067,
L00004A0064, L00005A0035, L00000A0189, L00000A0192, L00001A0154,
L00001A0155, L00002A0172, L00002A0173, L00003A0117, L00003A0118,
L00003A0119, L00004A0107, L00004A0108, L00004A0109, L00004A0110,
L00005A0078, L00005A0079, L00005A0080, L00006A0127, L00006A0128,
L00006A0129, L00006A0130, L00006A0131, L00006A0132, L00006A0133,
L00000A0201, L00000A0202, L00001A0161, L00001A0163, L00002A0175,
L00003A0126, L00004A0115, L00005A0085, L00006A0150, L00006A0151,
L00006A0152, L00006A0153, L00000A0197, L00000A0198, L00001A0158,
L00001A0159, L00002A0177, L00003A0124, L00004A0113, L00005A0083,
L00006A0142, L00006A0143, L00006A0144, L00006A0145, L00000A0193,
L00000A0194, L00001A0156, L00006A0155, L00006A0156, L00002A0174,
L00003A0120, L00003A0121, L00004A0111, L00005A0081, L00006A0134,
L00006A0135, L00006A0136, L00006A0137, L00000A0195, L00000A0196,
L00001A0157, L00002A0176, L00003A0122, L00003A0123, L00004A0112,
L00005A0082, L00006A0138, L00006A0139, L00006A0140, L00006A0141,
L00000A0199, L00000A0200, L00001A0162, L00002A0179, L00003A0125,
L00004A0114, L00005A0084, L00006A0146, L00006A0147, L00006A0148,
L00006A0149, L00000A0203, L00000A0204, L00001A0164, L00002A0180,
L00003A0127, L00004A0116, L00005A0086, L00000A0205, L00000A0206,
L00001A0165, L00002A0181, L00003A0128, L00004A0117, L00005A0087,
L00006A0154, L00000A0253, L00000A0254, L00001A0199, L00002A0203,
L00003A0157, L00004A0145, L00005A0113, L00000A0257, L00000A0258,
L00001A0201, L00002A0205, L00003A0159, L00004A0147, L00005A0115,
L00000A0261, L00000A0262, L00001A0203, L00002A0207, L00003A0161,
L00004A0149, L00005A0117, L00000A0265, L00000A0266, L00001A0205,
L00002A0209, L00003A0163



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E244889
Report Reference E244889-20110705
Issue Date 2020-AUGUST-22

L00004A0151, L00005A0119, L00000A0255, L00000A0256, L00001A0200,
L00002A0204, L00003A0158, L00004A0146, L00005A0114, L00000A0259,
L00000A0260, L00001A0202, L00002A0206, L00003A0160, L00004A0148,
L00005A0116, L00000A0263, L00000A0264, L00001A0204, L00002A0208,
L00003A0162, L00004A0150, L00005A0118, L00003A0158, L00002A0225,
L00003A0189, L00003A0195, L00003A0196, L00004A0167, L00003A0202,
L00005A0127, L00006A0309, L00006A0311, L00006A0305, L00004A0170,
L00006A0307, L00006A0313, L00006A0302, L00006A0306, L00004A0171,
L00006A0312, L00006A0310, L00006A0303, L00005A0126, L00006A0308,
L00006A0314, L00006A0304, L00004A0176, L00004A0177, L00005A0128,
L00006A0315, L00006A0316, L00003A0210, L00004A0192, L00005A0140,
L00000M0072, L00000A0329, L00006A0367, L00006A0368, L00006A0369,
L00001A0271, L00006A0394, L00000A0355, L00001A0276, L00000A0356,
L00001A0275, L00002A0269, L00003A0238, L00005A0159, L00000A0338,
L00000A0339, L00001A0261, L00001A0262, L00002A0256, L00002A0257,
L00003A0229, L00004A0205, L00005A0152, L00006A0354, L00006A0356,
L00006A0357, L00000A0340, L00000A0341, L00001A0263, L00001A0264,
L00002A0258, L00002A0259, L00003A0230, L00004A0206, L00005A0153,
L00006A0358, L00006A0359, L00006A0360, L00000A0342, L00000A0343,
L00001A0265, L00001A0266, L00002A0260, L00002A0261, L00003A0231,
L00004A0207, L00005A0154, L00006A0361, L00006A0362, L00006A0363,
L00000A0344, L00000A0345, L00001A0267, L00001A0268, L00002A0262,
L00002A0263, L00003A0232, L00004A0208, L00005A0155, L00006A0364,
L00006A0365, L00006A0366, L00006A0398, L00002A0270, L00005A0164,
L00006A0406, L00006A0397, L00006A0396, L00000A0388, L00000A0374,
L00000A0375, L00001A0286, L00001A0287, L00002A0280, L00002A0281,
L00003A0249, L00004A0224, L00005A0175, L00000A0376, L00000A0377,
L00001A0288, L00001A0289, L00002A0282, L00002A0283, L00003A0250,
L00004A0225, L00005A0176, L00000A0378, L00000A0379, L00001A0290,
L00001A0291, L00002A0284, L00002A0285, L00003A0251, L00004A0226,
L00005A0177, L00000A0380, L00000A0381, L00001A0292, L00001A0293,
L00002A0286, L00002A0287, L00003A0252, L00004A0227, L00005A0178,
L00006A0421, L00006A0422, JT0320F0A6040



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E244889
Report Reference E244889-20110705
Issue Date 2020-AUGUST-22

L00001A0309, L00002A0291, L00006A0424, L00006A0425, L00000A0406,
L80400A0000, L80401A0000, L80402A0000, L80403A0000, L80404A0000,
L80405A0000, L80406A0000, L80406A0001, L80406A0002, L00000A0413,
L80000A0002, L80001A0001, L80003A0001, L80004A0001, L80005A0001,
L80006A0001, L80006A0002, L80000A0000, L80000A0001, L80001A0000,
L80002A0000, L80003A0000, L80004A0000, L80005A0000, L80006A0000,
L80400A0002, L80401A0002, L80403A0002, L80404A0002, L80405A0002,
L80100A0002, L80100A0000, L80100A0001, L80101A0000, L80102A0000,
L80103A0000, L80104A0000, L80105A0000, L80400A0001, L80401A0001,
L80403A0001, L80404A0001, L80405A0001, L00000A0285, L00000A0149,
L00001A0139, L00002A0156, L00003A0098, L00004A0084, L00005A0058,
L00006A0099, L00006A0318, L00006A0319, L00000A0141, L00001A0133,
L00002A0150, L00003A0091, L00004A0090, L00005A0064, L00006A0105,
L83500A0000, L83500A0001, L83501A0000, L83502A0000, L83503A0000,
L83504A0000, L83505A0000, L00000A0422, L00002A0304, L80406A0003,
L80006A0003, L00003A0278, L80003A0003, L80403A0005, L80400A0004,
L80400A0003, L80401A0003, L80402A0001, L80403A0003, L80404A0003,
L80405A0003, L80406A0004, L80406A0005, L80406A0006, L80400A0005,
L80401A0005, L80403A0004, L80404A0004, L80405A0004

Modular patch cords: L00000A0503, L00000A0505, L00006A0483, L80406A0016,
L00000A0509, L00000A0512, L80100A0008

Modular Patch Cord: L00000A0513, L00001A0357, L00006A0497



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

